






A diagram of a cylinder with a height of 1 and a radius of 0.12. The cylinder is shown in a perspective view, with its base on a horizontal line. The height is labeled as 1, and the radius is labeled as 0.12.





A technical drawing of a bolted joint. It shows a bolt passing through a plate into a base. The bolt has a hexagonal head. Labels 'Z', 'P4', and 'N' are present. 'Z' is near the bolt head, 'P4' is near the bolt shank, and 'N' is near the base. An arrow points from 'N' to the base.












MARTIN – MA1	6/6
--------------	-----


An illustration showing two construction workers on the left, one holding a long level. To their right, a large speech bubble contains a collection of various tools: a level, a pencil, a hammer, a screwdriver with a plus sign, a power drill, a tape measure, a mallet, and a screwdriver with a minus sign.



#	ART. NR	L	W	T	Q	Col.No
1	7600	1930	500	16	1	1
2	7601	1930	500	16	1	1
3	7602	850	500	16	1	1
4	7603	818	480	16	2	1
5	7604	818	70	16	1	1
6	7605	818	230	16	1	1
7	7606	1868	416	2,5	2	1
8	7607	1430	476	--	1	2
9	7608	1430	476	--	1	2
10	7609	300	476	16	1	2
11	7610	300	476	16	1	2
12	7611	150	476	16	1	2
13	7612	150	476	16	1	2
14	7613	150	476	16	1	2





 A	 A1	 B	 C	 D1	 D2	 E	 E1	 G6	 F6	 F1
16	6	4	20	12	4	20	4	8	1	5
 L	 O	 P1	 P4	 P9	 R7	 N	 Z	 O10	 O12	 Z
10	1	20	3	16	4	1	1	2	1	1





	
S1	S
1	1

MARTIN – MA1	1/6
--------------	-----



1



2



3



7 | B

